


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-044	Smoke	9/5/2008	ADS/TM	S13GG1008MH	Dry	Yes	528.13



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-044	Smoke	9/5/2008	ADS/TM	S13GG1008MH	Dry	Yes	528.13

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13GG1031G1	S13GG1031DE	S13GG1008MH	84.90193	8
S15GG1032G1	S15GG1032MH	S15GG1011MH	140.2329	8
S13GG1008G1	S13GG1008MH	S15GG1032MH	302.9939	8

Observations & Photos

Obs_ID S1028-044-OB01

Address 2615 Park Heights Terr

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13GG1008MH

Comments Smoke from cleanout in front yard. 2615 Park Heights Terr



Picture \S1028-044-OB01-P01.jpg

Comments Front of house, 2615 Park Heights Terr

Obs_ID S1028-044-OB02

Address 2600 Park Heights Terr

Status Public

Source Catch Basin

Location Curb

Nearest MH S15GG1032MH

Comments Smoke from catch basin on NW corner of Park Heights Terr & Pall Mall Rd



Picture \S1028-044-OB02-P01.jpg

Comments Park Heights Terr & Pall Mall Rd looking north

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-044	Smoke	9/5/2008	ADS/TM	S13GG1008MH	Dry	Yes	528.13

Obs_ID S1028-044-OB03

Address 2603 Park Heights Terr


Status Public

Source Catch Basin

Location Curb

Nearest MH S15GG1032MH

Comments Smoke from catch basin on SW corner of Park Heights Terr & Pall Mall Rd



Picture \S1028-044-OB03-P01.jpg

Comments Park Heights Terr & Pall Mall Rd looking south

Obs_ID S1028-044-OB05

Address 2601 Park Heights Terr


Status Public

Source Catch Basin

Location Curb

Nearest MH S15GG1032MH

Comments Smoke from catch basin on curb. 2601 Park Heights Terr



Picture \S1028-044-OB05-P01.jpg

Comments Side of house (catch basin on left), 2601 Park Heights Terr

Obs_ID S1028-044-OB04

Address 2601 Park Heights Terr

Status Public

Source Catch Basin

Location Curb

Nearest MH S15GG1032MH

Comments Smoke from catch basin on SW corner of Park Heights Terr & Pall Mall Rd



Picture \S1028-044-OB04-P01.jpg

Comments Park Heights Terr & Pall Mall Rd looking south

Obs_ID S1028-044-OB06

Address 2601 Park Heights Terr


Status Public

Source Catch Basin

Location Curb

Nearest MH S15GG1032MH

Comments Smoke from catch basin on curb. 2601 Park Heights Terr



Picture \S1028-044-OB06-P01.jpg

Comments Side of house (catch basin on right), 2601 Park Heights Terr

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-044	Smoke	9/5/2008	ADS/TM	S13GG1008MH	Dry	Yes	528.13

Obs_ID S1028-044-OB07

Address 2549 Park Heights Terr

Status Public

Source Catch Basin

Location Curb

Nearest MH S15GG1032MH

Comments Smoke from catch basin along curb. 2549 Park Heights Terr



Picture \S1028-044-OB07-P01.jpg

Comments Side of house, 2549 Park Heights Terr
